

. = 62

In the United States Patent and Trademark Office

7.228.843

Group Art Unit: 3747

Inventors: G. Osburg et al

Examiner: Arnold Castro

Issued: June 12, 2007

Attorney Docket: A 91832

For: Internal Combustion Engine

having a Carburetor and a

Starting Device

Request for Certificate of Correction Pursuant to 37 CFR 1.322

Certificate

Commissioner for Patents and Trademarks

P.O. Box 1450

JUL 0 3 2007

Alexandria, Virginia 22313-1450

of Correction

Attention: Decision and Certificate of Correction

Branch of the Patent Issue Division

Dear Sir:

Transmitted herewith is a proposed certificate of correction for United States Patent 7,228,843 issued on June 12, 2007.

A printing error occurred in the patent which should be corrected as follows:

In column 4:

Line 37: insert -- to -- after "channel".

On behalf of the inventors and the assignee of record, Andreas Stihl AG & Co. KG, it is respectfully requested that the certificate of correction be approved pursuant to 37 CFR 1.322 and that

JUL 3 2007

an approved copy thereof be sent to the attorney of record at the address shown below.

Respectfully submitted,

Walter Ottesen

Reg. No. 25,544

Walter Ottesen Patent Attorney P.O. Box 4026

Gaithersburg, Maryland 20885-4026

Phone: (301) 869-8950

Date: June 28, 2007

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

7.228.843 PATENT NO. :

DATED : June 12, 2007

INVENTOR(S): Gerhard Osburg and Wolfgang Luithardt

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

> In column 4: Line 37: insert -- to -- after "channel".

MAILING ADDRESS OF SENDER:

Walter Ottesen Patent Attorney P.O. Box 4026

Gaithersburg, Maryland 20885-4026

FORM PTO 1050 (REV. 3-82)

PATENT NO. 7,228,843

No. of add'l. copies

@ 30c per page